

SERVICE BULLETIN

THROTTLE CABLE Z BEND PULLED OUT

NO. SD2

DATE: 7/31/14

RE: All surface drive engines

PROBLEM: Z bend pulled out of ball on end of cable.

CONDITION FOUND: Cable was frozen and Z bend pulled out.

SOLUTION: Add Z bend made from inner wire to end of cable which can be purchased at Go-Devil.

Note: After Z bend is installed it will be necessary to readjust the outer cable clamp on the throttle cable.

