

MEMO

LOWER BUSHING NOISE

NO. 19

DATE: 10/10/03 UPDATED 4/14/16

RE: ALL GO-DEVIL MODELS

On Go-Devils equipped with the new seal system, some customers report hearing a vibration coming from the lower bushing when running the Go-Devil out of the water. This is normal and does not indicate a problem with the Go-Devil. This condition is a result of the Lower Housing Flange Bushing floating and vibrating in the housing. The Lower Housing Flange Bushing is in place to keep debris out of the seals. The noise occurs when the Go-Devil is dry and will be eliminated when the engine is put in the water. This vibration can also be eliminated by spraying WD-40 on the Lower Housing Flange Bushing when servicing the engine. **WE HAVE NOW REPLACED THE LOWER FLANGE BUSHING WITH A SCRAPER SEAL.**