

# **SERVICE BULLETIN**

## **35 HP CRANKCASE LEAKING**

**NO. 18**

**DATE: 4/14/16**

**RE: 35 HP VANGUARD ENGINES**

**PROBLEM: CRANKCASE LEAKING OIL**

**CONDITION FOUND: GASKET FAILED**

**SOLUTION: Replace with new red gasket Briggs Part# 847133**

**Note: all engines built after march 2014 at Briggs & Stratton have a liquid gasket. The red gasket cannot be used on these engines.**