

**GO-DEVIL® MANUFACTURERS OF
LOUISIANA, INC.**

18649 Womack Road * Baton Rouge, La 70817
(225) 752-0167 * Fax (225) 752-0175
www.godevil.com

SERVICE BULLETIN

THROTTLE FREEZING SURFACE DRIVE

NO. 1SD

DATE: 07/30/2007

RE: All surface drive engines

PROBLEM: Throttle cable freezing and will not operate in freezing temperatures.

CONDITION FOUND: Moisture has entered cable.

SOLUTION: Raise handle to vertical position. Using a hypodermic syringe, inject some antifreeze down the side of the inner throttle cable. This will prevent the cable from freezing.