

SERVICE BULLETIN

PLASTIC FUEL CONNECTOR FAILURE

NO. 15

DATE: 7/31/14

RE: All engines using remote tank

PROBLEM: Engine dies runs out of gas air bubbles in fuel filter

CONDITION FOUND: O-ring failure in hose connector

SOLUTION: Replace hose connector and tank fitting with Suzuki style metal connectors. Suzuki style ¼" hose connectors (female) are not available in the market place. We have had them custom made and are available through Go-Devil. The ¼" (male) npt tank fitting is available in the market place. As of 6/20/14 all of our engines and boat rigs will ship with both Suzuki style connectors.