

**GO-DEVIL® MANUFACTURERS OF
LOUISIANA, INC.**

18649 Womack Road * Baton Rouge, La 70817
(225) 752-0167 * Fax (225) 752-0175
www.godevil.com

SERVICE BULLETIN

HANDLE HITS SEAT

NO. 4

DATE: 03/26/97

RE: ALL GO-DEVIL MODELS

PROBLEM: Tiller handle on Go-Devil hits rear seat when attempting to raise propeller to neutral position.

CONDITION FOUND: Rear seat in boat is either too high or too far to the rear of the boat to operate the Go-Devil properly.

SOLUTION: Remove standard tiller handle and install current model handle. If this does not correct problem handle may have to be cut and modified to customers boat.