

# **SERVICE BULLETIN**

---

## **LUBE KIT**

**NO. 5**

**DATE: 03/26/97**

**RE:** ALL GO-DEVIL MODELS BUILT BEFORE FEBRUARY 1<sup>ST</sup> 1997

**PROBLEM:** Lubrication required every four to six hours of running time and grease leaking around upper seal collar to relieve pressure.

**CONDITION FOUND:** Grease has no where to go when it expands during operation.

**SOLUTION:** Install LUBE KIT on Go-Devil.

LUBE KITS can be installed on all Go-Devil models that we have manufactured. This will eliminate the grease leaking around the upper seal collar and will hold a constant pressure of grease on the shaft system, including the lower bushing, at all times, as long as the lubricator is properly serviced. After testing these kits on various customers Go-Devils, we have found that the shaft and bushing life is greatly extended due to the constant lubrication.

The available kit is a weld-on.

**ALL GO-DEVIL MODELS SHIPPED AFTER FEBRUARY 1, 1997, ARE  
EQUIPPED WITH A LUBRICATOR.**